

Material Safety Data Sheet

May be used to comply with
 OSHA'S Hazard Communication Standard
 29 CFR 1910.1200. Standard must be
 consulted for specific requirements.

MOTHERS® POLISHES•WAXES•CLEANERS

5456 Industrial Drive
 Huntington Beach, Ca. 92649
 Telephone No. for Information: 714-891-3364
 Fax No. 714-893-1827
 Date Prepared 2/5/05

PRODUCT WHEEL MIST MULTI PURPOSE

PART NO. 05922

05902

05904

35922

05924

HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components (Specific Chemical Identity; Common Name(s) OSHA PEL ACGIH TLV Other Limits % (optional)

OXALIC ACID CAS # 144627

DODECYL BENZENE SULPHONIC ACID CAS # 27176-87-0

2 BUTOXYETHANOL CAS # 111-76-2 50 P/Ma

PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point	N/D	Specific Gravity (H2O = 1)	1.0900
---------------	-----	----------------------------	--------

Vapor Pressure (mm Hg.)	N/D	Melting Point	N/A
-------------------------	-----	---------------	-----

Vapor Density (air = 1)	N/D	Evaporation Rate (Butyl Acetate = 1)	N/A
-------------------------	-----	--------------------------------------	-----

Solubility in Water

Appearance and Odor ACIDIC CLEAR LIQUID, NEGLIGIBLE ODOR

FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used) N/A

Extinguishing Media N/A

Special Fire Fighting Procedures N/A

Unusual Fire and Explosion Hazards N/A

REACTIVITY DATA		PART NO.	05922
			05902
STABILITY	Unstable	Conditions to Avoid	05904
	Stable X		35922
Incompatibility (Materials to Avoid) _____			
Hazardous Decomposition or By-Products			
Hazardous	YES	X	Conditions to avoid AVOID CONTACT WITH STRONG
Polymerization	NO		BASE OR CAUSTIC MATERIALS
HEALTH HAZARD DATA			
Route(s) of Entry			
	Inhalation?	Skin?	Ingestion?
		X	X
Health Hazards (Acute and Chronic)		POSSIBLE SKIN IRRITATION	
		POSSIBLE EYE DAMAGE	
Carcinogenicity:	NTP?	IARC Monographs?	OSHA Regulated?
	NONE ES	0	NO
Signs and Symptoms of Exposure		RASH AND BURNING ON SKIN. IMMEDIATE EYE IRRITATION	
Medical Conditions Generally		NONE DETERMINED	
Aggravated by Exposure			
Emergency and First Aid Proceedures		INGESTION: DRINK LARGE QUANTITIES OF MILK.	
DO NOT INDUCE VOMITING. SEEK MEDICAL ATTENTION IMMEDIATELY. EYE CONTACT: FLUSH EYES			
WITH WATER FOR 15 MINUTES. SEEK MEDICAL ATTENTION IMMEDIATELY			
PRECAUTIONS FOR SAFE HANDLING AND USE			
Steps to Be Taken in Case Material Is Released or Spilled		ACIDIC PRODUCT DILUTE WITH	
WATER AND SOAK UP SPILL. WASH AREA THOROUGHLY. WEAR PROTECTIVE CLOTHING			
Waste Disposal Method		ACCORDING TO FEDERAL AND LOCAL LAWS	
Precautions to Be Taken In Handling and Storing		STORE IN A COOL DRY PLACE	
DO NOT STORE WITH BASE OR CAUSTIC MATERIAL			
Other Precautions			
AVOID SKIN AND EYE CONTACT			
Control Measures			
Respiratory Protection (Specify Type)			
Ventilation	Local Exhaust		
	Mechanical (General)	X	
Protective Gloves	RUBBER GLOVES	Eye Protection	SAFTEY GOGGLES
Other Protective Clothing or Equipment		RUBBER APRON AND BOOTS	
Work/Hygienic Practices		WASH HANDS AND EQUIPMENT THOROUGHLY AFTER USE	